

Cambria Community Services District



Board of Directors Regular Meeting
December 14, 2017

Facilities & Resources Department



The staff has been working on the park to get it ready for the grand opening. Pictures include delineation of the parking lot, cobble stone placement on middle drainage area, delivery and spreading of wood chips and installation of boulders.

We were supposed to get a delivery of cobbles to finish off the middle drainage, but unfortunately the delivery truck broke down and could not deliver them. They should be here next week. This is the final item to be completed.










Wastewater Department




The department emptied and cleaned all three ponds in preparation of the winter rains.



This manhole is one of the manhole we have identified as having problems. The manhole is leaking water even during the dry season. The cost to repair the leak is \$6,000 and we have several just like this one. The leak is coming from the connection 4 feet up from the bottom. This is not something that replacing the lid can fix.



This pressure relief valve will be used on the non-potable water system.



This is a snapshot of the GIS map for the collection system. This program has been one of the most helpful things added to the collection system. The department can step onto a manhole and find out what needs to be done and what has been done over the last year.

Engineering Department



Liner work is complete along the north side of the basin. Liner work is continuing on swale to the east of the impoundment basin.



