

CAMBRIA COMMUNITY SERVICES DISTRICT




Board of Directors Regular Meeting

January 18, 2018


Water Department – Stuart Street Tank Project



Superior Tank removed the most severely corroded roofing. After removal of the roof and a bunch of the rust scale, it was determined that 3 shell panels were too far gone to bolt to. Everyone agreed that changing the contract to add the replacement of those shell panels would increase the likelihood that this tank can stay in service for the desired 5 more years. The cost and schedule to change out the panels while Superior was on site, with the adjacent roof off, is significantly lower than having them come back later.













This pressure regulator is located at SS3. The water that goes through the regulator is for the chlorine analyzer and the turbidimeter for the entire SS wellfield.